

AP SURFACE MOUNT KIT (SMK)

INSTALLATION INSTRUCTIONS




WARNING:


- This product must be installed in accordance with the applicable installation code by a person familiar with the construction and operation of the product and the hazards involved.
- Make sure all electrical power is turned off while installing the fixture.
- This luminaire must be adequately grounded for protection against shock hazards and to assure proper operation.
- Disconnect power before servicing.
- LEDs are ESD (Electro Static Discharge) sensitive devices that can be easily damaged if the proper ESD mitigating steps are not taken.
- LEDs are very sensitive to mechanical damage. Caution must be taken to avoid damage to the LEDs.
- ESD or mechanical damage voids all warranties.
- Suitable for dry and damp locations.

SURFACE MOUNT INSTALLATION




STEP 1: Assemble kit with provided flat head screws. Secure to ceiling (screws provided by others).



STEP 2: Remove one end plate and wire fixture. Be sure to provide adequate length of flexible conduit and slide AP into side rails.



STEP 3: Attach end plate.



WIRING DIAGRAM

Make electrical connections in accordance with NEC and local codes.

Driver/power supply disconnects accept #12 – #16 AWG stranded or solid wire.
Attach power supply and ground wires using UL listed wire connectors.
Please consult factory for other driver configurations or emergency driver wiring diagrams.

